

## EPA Region 1 Clean Water Act Inspection Data Entry Form: 3560EZ

Version 1.05

Inspector:		George Harding		Date form completed		l:	9/30/2014		
Section A: Facility Information									
Inspection start date:		9/30/2014	Ins	Inspection start time:		9:30			
Inspection end date (if more than one day):		9/30/2014	Ins	Inspection finish time:		12:30			
NPDES ID:		MA0004898	Federal facility?		No				
Name and	Location of I								
	Name:	Veolia Kendall Green Energy LLC (formerly NRG Energy, or Mirant Kendall Cogeneration Station)							
	Address:	265 First Street							
	City:	Cambridge		State:	MA	ZIP:	02142		
Facility Re	presentative	#1:							
	Name:	Robert Richards		Title: EH and S Program Manager, Kendall Station		n Manager, Kendall			
	Address (if off-site):	As above.							
	City:	Enter text		State:	Enter text	ZIP:	Enter text		
	Phone #:	(617) 679-4818		Email:	Robert.Rich	nards@	veolia.com		
Facility Re	presentative	#2 (if necessary):							
	Name:	Sean Caldwell	Title:	Director, EHS, Veolia					
	Address (if off-site):	15 Elkins Street							
	City:	Boston		State:	MA	ZIP:	02127		
	Phone #:	(857) 401-9842		Email:	Sean.caldw	ell@v	eolia.com		
Section B:	Compliance	Monitoring Information							
Clean Wat	er Act Sectio	n (choose from only one of the fo	llow	ing):					
	CWA §308[A][B]: NPDES			Base Program (Limits, Reporting, Schedule)					
	CWA §311: Oil and Hazardous Substances		Choose an item						
	CWA §404: Material	WA §404: Permits for Dredge and Fill aterial			Choose an item				
Complianc	e Monitoring	Type:	Compliance Evaluation Inspection (CEI)			tion (CEI)			
Compliance	e Monitoring	Reason:	Co	Core Program					
	If Agency Priority, then specify priority(s):								
	(	OECA - CAFO							
	(	.S							
	(	DECA - CSOs w/ < 50,000 service							
	OECA - CSOs w/ $>= 50,000$ ser			ice population					
	OECA - MS4s Phase I								

	OECA - MS4s Phase II						
	OECA - SSOs ≥ 10 MGD and < 100 MGD						
	Region 1 - Environmental Justice						
	Region 1 - Green Economy / Green Infrastructure						
	Region 1 - Industrial Laundries						
	Region 1 - Lead Poisoning						
	Region 1 - Municipal Infrastructure						
	Region 1 - Pollution Prevention & Resource Conservation						
	Region 1 - Ship / Boat Yards						
	Region 1 - Wet Weather						
Compliance Monit							
	ompliance Monitoring Activity?	No					
	, which party had the lead?	Choose an iten	n or leave blank if N/A				
	If State lead, what was the purpose of EPA	Change on item	1 1- 1 1 1- X/A				
	participation? Choose an iter						
Section C: ICDS	Information						
Did you observe d	eficiencies (potential violations) during the inspection	?	No				
Potenti	al excess emission in violation of regulations:						
	al failure to						
	plete or submit a notification, report, certification, or	manifest:					
	ow a permit condition(s):						
	ow a required sample monitoring procedure or laborate						
	ow or develop a required management practice or proc						
	identify and manage a regulated waste or pollutant in any media:						
	ntain a record or failure to disclose a document:						
mai	maintain/inspect/repair meters, sensors, and recording equipment:						
obta	in a permit, product approval, or certification:						
repo	report regulated events such as spills, accidents, etc.:						
	Potential incorrect use of a material (pesticide, waste, product) or use of an unapproved material:						
	Potential violation of a compliance schedule in an enforceable order:						
If you observed de during the inspecti	No						
	did you observe the Facility take any actions during the deficiencies noted?	No					
	If yes, what actions were taken? Implemented procedures	l management practices or					
	Metals in stormwater						
Did you provide go role of the EPA in	No						
Did you provide sittle role of the EPA	No						
Comments:							
Enter text							